
TYPICAL AIR INSTALLATIONS





turbine starter with air pressure greater than the pressure rating on the nameplate.



COAST DOWN PERIOD

After a failed start attempt wait at least 30 seconds prior to the next start attempt. This is required in order for the turbine starter to stop rotating.



55-59005 Quick Exhaust Valve

Pow-R-Quik

A Division of Maradyne Corporation 4540 West 160th Street Cleveland, OH 44135 PH: 216-362-0755 Fax:216-362-0799

Website - www.powrquik.com

Email - sales@powrquik.com